


Art.no 481-11


FIRST USE

STEP 1.




NOTE : ground pin
inside the body

STEP 2.



ON : Press 3 seconds











- ON 1 : Press 1 time 70Lm steady ON / motion sensor off
- ON 2 : Press +1 time 70Lm steady ON / motion sensor ON (p 2)
- ON 3 : Press +1 time 70Lm steady OFF / motion sensor ON (p 2)



OFF : Press 3 seconds

Ready after
36 h in the sun

BATTERY REPLACEMENT




STAR
TRADING

STAR STREET 1
512 50 SVENLJUNGA
SWEDEN
www.startrading.com

Art No: 481-11

70 LUMEN CONSTANT LIGHT

MOTION SENSOR 500 LUMEN FOR 25 SEK




FUNCTION

ON 1 : Press 1 time 70Lm steady ON / motion sensor off

ON 2 : Press +1 time 70Lm steady ON / motion sensor ON (500Lm for 25 sec)

ON 3 : Press +1 time 70Lm steady OFF / motion sensor ON (500Lm for 25 sec)

OFF : Press 3 seconds



STAR
TRADING
STAR STREET 1
512 50 SVENLJUNGA
SWEDEN
www.startrading.com